

Test Report No.: SZXEC25002459203 **Date**: Jul 15, 2025 Page 1 of 4

Client Name: SHENZHEN TANI SEMICONDUCTOR CO., LTD.

Client Address: 6TH FLOOR H, BLOCK A, HUAQIANG PLAZA, 1019 HUAQIANG NORTH ROAD, FUTIAN

DISTRICT, SHENZHEN

Sample Name: LDO

Model No.: SOT89-3

Client Ref. Information: SOT89 STO89-2 SOT89-3 SOT89-5 TO247(TO3P) TO220AB TO220F

TO-277 TO-251 TO-92 DIP-4 DIP-8 SOP-4 SOP-6 SOP-7 SOP-8 SOP-10

SOP-14 SOP-16 TSSOP-20 SOP-28 MSOP-8L TO-263 SOT-23-6 SOT-23-3 SOD-123 SC70-5 (SOT-353) SOT23-5 SOD-523 SOD-323 SOD-323HE SOD-123F TO-252-2 SOT-223-3 PDFN3333 LGA-12(2x2) DFN2510-10 DFN-6 DFN1006 QFN-16-EP(3x3) DFN-4L(1x1) PDFN5x6 WBFBP-03E DFN-3L(1x0.6) SMA SMB SMC SMBF SMAF UMSB MBS

MBF KBP DBS ABS

The above sample(s) and information were provided by the client.

The above sample(s) and information were provided by the olient.

SGS Job No.: SZP25-034645
Reference No.: SHP25-022885
Sample Receiving Date: Jul 09, 2025

Testing Period: Jul 09, 2025 ~ Jul 15, 2025

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).

Test Result(s): Please refer to next page(s).

Test Requirement	Conclusion
Halogen	See Results

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

May

May Bei

Approved Signatory





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. And unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Roum 101-901, Plant 4 & Roum 101, Plant 2 & Roum 101, Plant 3 & Roum 101-01, Plant 4 & Roum 101-01, Plant 4 & Roum 101-01, Plant 3 & Roum 101-01, Plant 4 & Roum 101-01, Plant 4 & Roum 101-01, Plant 3 & Roum 101-01, Plant 4 & Roum 101-01, Plant 3 & Rou



Test Report No.: SZXEC25002459203 **Date**: Jul 15, 2025 Page 2 of 4

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	SZX25-0024592-0001.C001	"LDO"

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Halogen

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A1
Fluorine(F)	mg/kg	20	ND
Chlorine(CI)	mg/kg	50	ND
Bromine(Br)	mg/kg	50	ND
lodine(I)	mg/kg	50	ND

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.




Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior writine approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101-901, Plant 4 & Room 101, Plant 2 & Room 101, Plant 2 & Room 101, Plant 3, Room 301-301, Plant 3, Langhao Bendian) Industrial Plant Area, No. 401, Illius Read, Barlian Community, Barlian Street, Longsang Distric, Shenzhen, Guargdong, China 1818/2 www.sepsgroup.com.cn 中国 - 广东 - 深圳市龙岗区坂田街道坂田社区吉年路430号江瀛(坂田)工业厂区厂房4号101—901、2号101、3号301—501 单编:518129 t(86-755) 25328888 sgs.china@sgs.com



Test Report ATTACHMENTS

Halogen Testing Flow Chart






Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior writine approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com



Sample Photo:



SGS authenticate the photo on original report only

*** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior writine approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Roum 101-901, Plant 4 & Room 101, Plant 2 & Room 101, Plant 2 & Room 101, Plant 3, Room 301-301, Plant 3, Langhao Bendian) Industrial Plant Area, No. 403, Illiua Read, Barifae Community, Bantian Steet, Longsang Districk, Shenzhen, Guanpdong, China 181812 www.sepsgroup.com.cn 中国 - 广东 - 深圳市龙岗区坂田街道坂田社区吉年路430号江瀛(坂田)工业厂区厂房4号101-901、2号101、3号301-501 樟编:518129 t(86-755) 25328888 sps.china@sps.com